

取扱注意

この資料は、土地区画整理事業に伴う換地処分時の測量成果(日本測地系)ですので、あくまで参考資料として取り扱ってください。

| 座標リスト(基準点) |             |           |       |             |           |
|------------|-------------|-----------|-------|-------------|-----------|
| NO.        | X           | Y         |       |             |           |
| 30108      | -129123.189 | 81879.265 | T3096 | -130867.964 | 81600.951 |
| 30110      | -129959.498 | 81772.404 | T3098 | -130914.024 | 81544.924 |
| 30111      | -130538.388 | 81447.795 | T3099 | -129843.445 | 81901.817 |
| 30120      | -130167.996 | 81827.194 | T3100 | -129807.345 | 81909.792 |
| 30121      | -130227.504 | 81972.901 | T3101 | -129767.801 | 81922.795 |
| 30122      | -129739.170 | 81994.514 | T3102 | -129738.356 | 81935.384 |
| 30210      | -129591.303 | 82069.728 | T3103 | -129708.264 | 81949.387 |
| 30307      | -130988.361 | 81459.257 | T3104 | -129676.084 | 81964.379 |
| 30320      | -130656.191 | 81763.630 | T3105 | -129637.215 | 81982.546 |
| 30321      | -130852.388 | 81649.669 | T3107 | -129557.459 | 81922.980 |
| NO.1       | -131297.593 | 81920.032 | T3110 | -129476.861 | 81892.109 |
| NT1012     | -129585.492 | 82120.270 | T3112 | -129516.890 | 81814.721 |
| NT1018     | -130657.909 | 81580.071 | T3114 | -129595.246 | 81810.433 |
| T3001      | -129352.033 | 81830.834 | T3116 | -129678.395 | 81805.571 |
| T3002      | -129556.158 | 81814.620 | T3119 | -129752.682 | 81897.029 |
| T3003      | -129727.295 | 81805.434 | T3122 | -129604.309 | 81919.562 |
| T3004      | -130053.184 | 81779.499 | T3128 | -129601.080 | 81848.035 |
| T3005      | -130184.569 | 81750.538 | T3132 | -130100.920 | 81767.390 |
| T3006      | -130762.422 | 81598.147 | T3133 | -130151.346 | 81752.078 |
| T3007      | -131195.248 | 81534.822 | T3137 | -130293.001 | 81763.657 |
| T3008      | -131099.496 | 81580.915 | T3138 | -130246.305 | 81775.612 |
| T3009      | -130964.250 | 81619.229 | T3145 | -130247.280 | 81920.924 |
| T3010      | -130545.452 | 81865.210 | T3146 | -130263.989 | 81971.304 |
| T3011      | -130509.873 | 81941.698 | T3152 | -130270.305 | 81916.227 |
| T3012      | -130390.729 | 81800.796 | T3159 | -129302.936 | 82135.185 |
| T3013      | -130288.823 | 81821.295 | T3160 | -129351.584 | 82115.309 |
| T3014      | -130005.901 | 82007.775 | T3163 | -129177.281 | 82135.167 |
| T3015      | -129879.813 | 82029.908 | T3172 | -129267.259 | 81910.832 |
| T3016      | -129148.216 | 82027.444 | T3175 | -129222.503 | 81980.695 |
| T3017      | -129201.916 | 82194.564 | T3178 | -129190.561 | 81994.943 |
| T3018      | -129350.076 | 82230.835 | T3179 | -129176.654 | 81960.511 |
| T3019      | -129266.562 | 82017.140 | T3180 | -129212.957 | 82061.329 |
| T3020      | -129890.085 | 81905.156 | T3181 | -129225.262 | 82103.398 |
| T3023      | -130396.436 | 81692.609 | T3183 | -129353.897 | 81886.165 |
| T3024      | -130452.081 | 81675.973 | T3200 | -129457.855 | 82079.590 |
| T3025      | -130457.855 | 81722.243 | T3201 | -130666.983 | 81790.958 |
| T3032      | -130343.467 | 81749.002 | T3202 | -130628.428 | 81818.907 |
| T3037      | -129965.793 | 82012.716 | T3203 | -130578.080 | 81854.376 |
| T3039      | -129874.823 | 81990.904 | T3205 | -130531.639 | 81823.827 |
| T3040      | -129882.433 | 81944.527 | T3209 | -129840.005 | 81960.779 |
| T3049      | -129916.830 | 81944.674 | T3210 | -129788.597 | 81965.283 |
| T3053      | -129714.274 | 82046.478 | T3211 | -129796.775 | 82003.150 |
| T3055      | -129624.194 | 82103.802 | T3212 | -129748.373 | 82035.372 |
| T3057      | -129503.437 | 82145.562 | T3214 | -129453.896 | 82033.374 |
| T3059      | -129481.103 | 82191.021 | T3215 | -129404.626 | 82034.082 |
| T3060      | -129456.329 | 82111.150 | T3216 | -129364.281 | 82032.950 |
| T3061      | -129513.749 | 82101.719 | T3217 | -129321.643 | 82044.039 |
| T3062      | -129558.436 | 82075.951 | T3218 | -129300.445 | 81994.080 |
| T3062      | -130417.649 | 81887.805 | T3220 | -129232.855 | 81927.208 |
| T3065      | -130378.982 | 81848.318 | T3221 | -129232.582 | 81884.598 |
| T3066      | -130415.432 | 81842.473 | T3222 | -129201.594 | 81900.091 |
| T3067      | -130455.074 | 81836.091 | T3223 | -129159.165 | 81919.368 |
| T3068      | -131169.790 | 81512.316 | T3224 | -129213.925 | 81935.083 |
| T3069      | -131131.342 | 81541.426 | T3225 | -129244.357 | 82018.983 |
| T3090      | -131091.700 | 81552.565 | T3226 | -129279.331 | 82083.539 |
| T3091      | -131146.938 | 81555.336 | T3227 | -129391.823 | 81830.641 |
| T3092      | -131044.344 | 81557.034 | T3228 | -129402.032 | 81879.737 |
| T3095      | -130908.827 | 81588.985 | T3229 | -129398.084 | 81933.010 |
|            |             |           | T3235 | -129657.893 | 82032.806 |
|            |             |           | T3238 | -129838.381 | 82034.592 |

取扱注意

この資料は、土地区画整理事業に伴う換地処分時の測量成果（日本測地系）ですので、あくまで参考資料として取り扱ってください。

|       |             |           |       |             |           |
|-------|-------------|-----------|-------|-------------|-----------|
| T3253 | -129246.707 | 82098.634 | T3506 | -130667.693 | 81626.173 |
| T3254 | -129228.658 | 82170.342 | T3507 | -130677.175 | 81662.304 |
| T3261 | -129821.226 | 81965.606 | T3508 | -130724.436 | 81649.702 |
| T3262 | -129685.562 | 82023.728 | T3510 | -130795.542 | 81626.800 |
| T3301 | -129999.399 | 81787.998 | T3511 | -130830.595 | 81613.744 |
| T3302 | -129956.386 | 81792.582 | T3512 | -130881.328 | 81698.627 |
| T3303 | -129902.341 | 81794.480 | T3516 | -130509.291 | 81952.115 |
| T3304 | -129854.389 | 81798.371 | T3517 | -130498.670 | 81974.898 |
| T3306 | -129780.828 | 81837.345 | T3519 | -130430.499 | 81951.496 |
| T3307 | -129810.234 | 81842.134 | T3520 | -130430.837 | 81921.729 |
| T3308 | -129868.666 | 81851.655 | T3521 | -130467.712 | 81914.756 |
| T3310 | -129943.457 | 81839.837 | T3522 | -130472.810 | 81946.845 |
| T3311 | -129982.020 | 81843.006 | T3523 | -129433.033 | 81951.860 |
| T3312 | -130032.119 | 81839.395 | T3524 | -129462.409 | 81951.757 |
| T3316 | -130283.730 | 81806.152 | T3525 | -129463.922 | 81930.373 |
| T3317 | -130241.184 | 81810.570 | T3526 | -129261.313 | 82050.519 |
| T3319 | -130068.917 | 81853.088 | T3529 | -129627.155 | 82046.837 |
| T3321 | -129156.960 | 82076.493 | T3530 | -130391.348 | 81743.449 |
| T3322 | -129122.478 | 81980.240 | T3531 | -130425.809 | 81729.792 |
| T3323 | -129116.103 | 81939.524 | T3532 | -130313.965 | 81801.635 |
| T3325 | -129484.270 | 81929.215 | T3533 | -130346.240 | 81793.590 |
| T3327 | -129437.446 | 81907.145 | T3534 | -130393.813 | 81786.678 |
| T3329 | -129440.836 | 81820.840 | T3535 | -130432.579 | 81780.729 |
| T3330 | -129474.139 | 81819.072 | T3536 | -130320.032 | 81761.765 |
| T3331 | -129991.676 | 81869.261 | T3537 | -131071.517 | 81592.207 |
| T3332 | -129947.186 | 81876.923 | T3538 | -131032.322 | 81602.658 |
| T3333 | -129480.361 | 81856.183 | T3541 | -130924.104 | 81627.899 |
| T3335 | -129307.829 | 82095.269 | T3602 | -130363.592 | 81807.061 |
| T3336 | -129324.248 | 82123.784 | T3603 | -130323.138 | 81813.678 |
| T3339 | -129346.172 | 82177.826 | T3605 | -130254.315 | 81828.127 |
| T3340 | -129334.290 | 82147.263 | T3606 | -130212.842 | 81836.775 |
| T3341 | -129351.565 | 82129.760 | T3607 | -130170.578 | 81846.535 |
| T3342 | -129402.210 | 82107.884 | T3608 | -130111.612 | 81857.957 |
| T3343 | -130462.866 | 81884.509 | T3609 | -130066.194 | 81868.160 |
| T3401 | -129690.206 | 81923.709 | T3610 | -130020.051 | 81877.533 |
| T3403 | -129624.087 | 81957.243 | T3611 | -129977.476 | 81887.440 |
| T3404 | -129626.705 | 81973.330 | T3612 | -129933.070 | 81896.286 |
| T3406 | -129721.426 | 81885.415 | T3613 | -130031.209 | 81860.815 |
| T3407 | -129779.857 | 82007.996 | T3614 | -129250.252 | 81966.745 |
| T3408 | -129772.797 | 81974.986 | T3615 | -129282.181 | 81957.955 |
| T3409 | -129763.568 | 81939.549 | T3616 | -130316.702 | 81916.808 |
| T3410 | -129803.884 | 81925.052 | T3617 | -130341.076 | 81914.295 |
| T3411 | -129850.828 | 81914.544 | T3619 | -129801.802 | 81962.316 |
| T3412 | -129719.001 | 81958.255 | T3620 | -129561.392 | 81967.481 |
| T3414 | -130654.643 | 81662.475 | T3621 | -129614.428 | 81991.611 |
| T3415 | -130662.333 | 81710.198 | T3622 | -129582.824 | 82005.184 |
| T3416 | -130665.677 | 81744.407 | T3623 | -129543.848 | 82023.992 |
| T3419 | -130568.461 | 81673.665 | T3624 | -129502.517 | 82043.497 |
| T3423 | -130612.310 | 81704.081 | T3625 | -129451.326 | 82066.599 |
| T3424 | -131187.517 | 81485.358 | T3626 | -129338.921 | 81979.507 |
| T3425 | -131132.042 | 81491.416 | T3627 | -129375.258 | 81981.223 |
| T3426 | -131101.583 | 81502.277 | T3628 | -129409.661 | 81978.216 |
| T3427 | -131057.667 | 81509.900 | T3632 | -129314.971 | 82019.802 |
| T3428 | -131011.529 | 81521.192 | T3633 | -130074.206 | 81904.311 |
| T3430 | -131219.977 | 81473.440 | T3639 | -129456.019 | 82153.325 |
| T3431 | -131206.834 | 81500.000 | T3641 | -129398.364 | 82187.215 |
| T3433 | -131068.396 | 81558.381 | T3642 | -129484.220 | 81986.722 |
| T3501 | -130861.372 | 81560.288 | T3646 | -130258.120 | 81946.530 |
| T3504 | -130739.117 | 81596.502 | T3649 | -129562.119 | 81886.638 |
| T3505 | -130707.296 | 81606.220 | T3650 | -129560.220 | 81851.769 |

取扱注意

この資料は、土地区画整理事業に伴う換地処分時の測量成果（日本測地系）ですので、あくまで参考資料として取り扱ってください。

|       |             |           |
|-------|-------------|-----------|
| T3702 | -130213.779 | 81932.966 |
| T3703 | -130207.153 | 81882.428 |
| T3704 | -130178.821 | 81886.890 |
| T3705 | -130148.650 | 81899.544 |
| T3706 | -130112.359 | 81901.818 |
| T3708 | -130157.744 | 81967.672 |
| T3709 | -130137.370 | 81949.616 |
| T3801 | -130954.297 | 81533.348 |
| T3802 | -130961.105 | 81575.840 |
| T3803 | -130999.370 | 81566.645 |
| T3804 | -130997.633 | 81611.527 |
| T3805 | -130815.204 | 81567.011 |
| T3806 | -130760.415 | 81641.954 |
| T3807 | -130878.426 | 81638.674 |
| T3809 | -130725.416 | 81724.881 |
| T3810 | -130690.682 | 81737.843 |
| T3811 | -130645.041 | 81623.505 |
| T3812 | -130599.048 | 81630.410 |
| T3814 | -130493.148 | 81829.889 |
| T3815 | -130330.135 | 81707.604 |
| T3816 | -130282.471 | 81726.064 |
| T3817 | -130239.895 | 81731.138 |
| T3818 | -130199.849 | 81787.566 |
| T3819 | -130169.835 | 81794.834 |
| T3820 | -130202.522 | 81820.512 |
| T3821 | -130121.753 | 81831.153 |
| T3822 | -130107.596 | 81844.733 |
| T3823 | -130056.851 | 81834.985 |
| T3824 | -129913.091 | 81845.501 |
| T3825 | -129800.617 | 81807.200 |
| T3826 | -130494.896 | 81878.752 |
| T3827 | -130361.660 | 81891.580 |
| T3828 | -130346.780 | 81853.475 |
| T3829 | -130458.239 | 81983.503 |
| T3830 | -129731.578 | 81846.499 |
| T3831 | -129742.963 | 81864.607 |
| T3833 | -129521.592 | 81890.217 |
| T3834 | -129443.422 | 81870.719 |
| T3836 | -129661.791 | 81935.959 |
| T3837 | -130300.529 | 81914.268 |
| T3838 | -130295.171 | 81863.443 |
| T3839 | -130251.261 | 81878.080 |
| T3841 | -130122.657 | 81931.848 |
| T3843 | -129437.243 | 81976.905 |
| T3844 | -130044.138 | 81985.592 |
| T3845 | -130001.390 | 81943.321 |
| T3846 | -129952.420 | 81943.029 |
| T3847 | -129916.878 | 82023.981 |
| T3848 | -129803.683 | 82036.921 |
| T3849 | -129706.262 | 82007.317 |
| T3850 | -129676.279 | 82067.893 |
| T3851 | -129534.013 | 82130.750 |
| T3852 | -129395.323 | 82145.662 |
| T3853 | -129357.357 | 82202.890 |
| T3854 | -129201.014 | 82020.755 |
| T3855 | -129138.002 | 81999.283 |
| T3856 | -129261.490 | 82155.568 |
| T3857 | -129294.505 | 82061.650 |
| T3858 | -129262.591 | 81861.593 |
| T3860 | -129311.710 | 81902.562 |

|       |             |           |
|-------|-------------|-----------|
| T3861 | -129320.027 | 81946.856 |
| T3862 | -129361.850 | 81942.810 |
| T3863 | -129428.265 | 81937.852 |
| T3864 | -129517.185 | 81932.653 |
| T3865 | -129516.487 | 81855.759 |
| T3866 | -129633.247 | 81903.792 |
| T3867 | -129661.372 | 81886.338 |
| T3868 | -129640.306 | 81863.052 |
| T3869 | -129603.125 | 81884.501 |
| T3870 | -129640.291 | 81809.933 |
| T3871 | -129692.015 | 81866.987 |
| T3872 | -129418.102 | 82083.187 |
| T3873 | -129385.619 | 82096.364 |
| T3874 | -130806.189 | 81670.480 |
| T3875 | -130766.612 | 81698.908 |
| T3876 | -130763.790 | 81556.024 |
| T3877 | -130556.137 | 81604.707 |
| T3878 | -130438.527 | 81649.566 |
| T3879 | -130223.432 | 82006.112 |
| T3882 | -130333.738 | 81974.132 |
| T3883 | -130369.189 | 81955.417 |
| T3884 | -130403.176 | 81946.866 |
| T3885 | -130566.773 | 81638.869 |
| T3886 | -130514.371 | 81665.074 |
| T3887 | -130485.494 | 81672.685 |
| T3889 | -130535.370 | 81715.869 |
| T3890 | -130113.666 | 81939.777 |
| T3892 | -130566.896 | 81815.756 |
| T3893 | -130076.027 | 81942.936 |
| T3898 | -129889.758 | 82067.927 |
| T3899 | -129873.226 | 82033.260 |
| T3900 | -129820.124 | 82037.634 |
| T3901 | -129776.659 | 82040.228 |
| T3902 | -129757.413 | 82062.786 |
| T3905 | -130527.270 | 81898.847 |
| T3906 | -130520.133 | 81869.336 |
| T3907 | -130545.599 | 81882.628 |
| T3908 | -129567.293 | 82134.275 |
| T3909 | -129524.089 | 82143.855 |
| T3910 | -129495.976 | 82162.751 |
| T3913 | -130264.272 | 82008.073 |
| T3914 | -130299.069 | 81997.159 |
| T3919 | -130559.726 | 81700.878 |
| T3920 | -130557.210 | 81683.036 |
| T3921 | -130554.227 | 81679.898 |
| T3922 | -130562.500 | 81674.088 |
| T3923 | -130534.847 | 81674.428 |
| T3924 | -130530.511 | 81657.729 |
| T3930 | -130515.126 | 81693.993 |
| T3931 | -130482.888 | 81700.836 |
| T3933 | -130382.308 | 81888.313 |
| T3934 | -130392.122 | 81918.944 |
| T3935 | -130352.177 | 81928.652 |
| T3936 | -130309.935 | 81935.442 |
| T3937 | -130342.881 | 81904.327 |
| T3938 | -129310.321 | 81842.197 |
| T3939 | -130202.244 | 81995.054 |
| T3940 | -130166.325 | 81997.694 |
| T3941 | -130632.330 | 81751.031 |
| T3942 | -130592.310 | 81758.418 |

取扱注意

この資料は、土地区画整理事業に伴う換地処分時の測量成果（日本測地系）ですので、あくまで参考資料として取り扱ってください。

|       |             |           |
|-------|-------------|-----------|
| T3943 | -130544.065 | 81765.549 |
| T3944 | -130507.469 | 81770.411 |
| T3945 | -130474.714 | 81773.483 |
| T3946 | -130622.487 | 81767.458 |
| T3947 | -130593.128 | 81771.930 |
| T3948 | -130566.674 | 81776.633 |
| T3949 | -130525.124 | 81781.405 |
| T3950 | -130491.788 | 81787.713 |
| T3951 | -130459.057 | 81790.532 |
| T3952 | -130422.294 | 81796.078 |
| T3953 | -130536.129 | 81764.198 |
| T3954 | -130524.700 | 81728.064 |
| T3955 | -130502.444 | 81740.521 |
| T3956 | -130469.724 | 81752.425 |
| T3957 | -130581.815 | 81736.278 |
| T3958 | -130583.833 | 81713.569 |
| T3959 | -130572.921 | 81694.495 |
| T3960 | -130226.904 | 82025.741 |
| T3961 | -130194.045 | 82018.369 |
| T3962 | -130158.153 | 82002.348 |
| T4001 | -129909.233 | 82032.524 |
| T4002 | -129949.341 | 82025.482 |
| T4003 | -130002.394 | 82015.005 |
| T4004 | -130032.874 | 81999.276 |
| T4005 | -130055.614 | 81985.321 |

取扱注意

この資料は、土地区画整理事業に伴う換地処分時の測量  
成果（日本測地系）ですので、あくまで参考資料として  
取り扱ってください。

成果表

地番：基準点

| 測点    | X           | Y         | S      | 方向角       |
|-------|-------------|-----------|--------|-----------|
| T3086 | -130415.432 | 81842.473 | 45.386 | 92-48-00  |
| T3082 | -130417.649 | 81887.805 | 36.397 | 111-14-37 |
| T3520 | -130430.837 | 81921.729 | 29.769 | 89-20-58  |
| T3519 | -130430.499 | 81951.496 | 27.713 | 350-22-56 |
| T3884 | -130403.176 | 81946.866 | 30.030 | 291-35-53 |
| T3934 | -130392.122 | 81918.944 | 32.165 | 287-45-55 |
| T3933 | -130382.308 | 81888.313 | 20.905 | 8-59-28   |
| T3827 | -130361.660 | 81891.580 | 64.279 | 96-43-35  |
| T3883 | -130369.189 | 81955.417 | 31.714 | 302-26-25 |
| T3935 | -130352.177 | 81928.652 | 49.076 | 67-55-51  |
| T3882 | -130333.738 | 81974.132 | 41.619 | 33-35-31  |
| T3914 | -130299.069 | 81997.159 | 36.468 | 17-24-50  |
| T3913 | -130264.272 | 82008.073 | 40.887 | 357-15-03 |
| T3879 | -130223.432 | 82006.112 | 33.460 | 263-00-35 |
| 30121 | -130227.504 | 81972.901 | 42.228 | 288-58-01 |
| T3702 | -130213.779 | 81932.966 | 50.971 | 277-28-10 |
| T3703 | -130207.153 | 81882.428 | 44.322 | 185-37-47 |
| T3839 | -130251.261 | 81878.080 | 43.029 | 84-41-29  |
| T3145 | -130247.280 | 81920.924 | 26.888 | 113-46-32 |
| T3646 | -130258.120 | 81945.530 | 26.434 | 102-49-41 |
| T3146 | -130263.989 | 81971.304 | 55.438 | 263-27-29 |
| T3152 | -130270.305 | 81916.227 | 30.387 | 183-41-47 |
| T3837 | -130300.629 | 81914.268 | 23.129 | 113-43-32 |
| T3936 | -130309.935 | 81935.442 | 19.825 | 250-02-29 |
| T3616 | -130316.702 | 81916.808 | 24.503 | 185-53-11 |
| T3617 | -130341.076 | 81914.295 | 10.130 | 259-44-10 |
| T3937 | -130342.881 | 81904.327 | 62.831 | 319-24-21 |
| T3838 | -130295.171 | 81863.443 | 52.563 | 190-55-54 |
| T3828 | -130346.780 | 81853.475 | 32.612 | 189-05-54 |
| T3085 | -130378.982 | 81848.318 | 36.916 | 189-06-37 |